

**General Data**

**Change Nr, Title** 20007911, Add UKCA marking  
**Date of issue** 28.06.2021

**Category of change**

- Materials
- Method
- Manufacturing place
- Machine
- Form
- Fit
- Function

**Affected products**

See appendix

**Description of change**

UKCA marking introduced on affected products.

**Reason for change**

Compliance regulation introduced in UK.

**Impact for the customer**

None.

**Identification**

UKCA marking is visible on product label, product box label and data sheet where applicable.



Figure 1: UKCA marking




Figure 2: Example product label before change




Figure 3: Example product label after change

**Estimated Schedule**

Applied on all new orders of affected products by end October 2021 the latest.

---

**Customer enquiries**

You may address any technical enquiries regarding this PCN by sending an E-Mail to [pcn@schaffner.com](mailto:pcn@schaffner.com). Please refer to the "Change number" on page 1 for faster response.

---

**Quality assurance measures**

Application of ISO9001:2015 and exceeding Schaffner standards for outstanding quality in all involved design centers and manufacturing locations.

---

Date of announcement

28.06.2021

**Schaffner Group**  
Nordstrasse 11e  
CH-4542 Luterbach  
[www.schaffner.com](http://www.schaffner.com)

## Appendix

### List of affected products

FN251	FN1393	FN3271H	FN3530	FN9233	FN9255	FN9292
FN256	FN1394	FN3280H	FN3531	FN9233B	FN9255B	FN9292B
FN258	FN2010	FN3280HL	FN3532	FN9233E	FN9255EB	FN9299
FN261	FN2020	FN3280HN	FN353Z	FN9233EB	FN9255EMB	FN9299B
FN281	FN2030	FN3280HQ1	FN3540	FN9233ER	FN9255ESB	FS3530
FN282	FN2060	FN3280HQ2	FN3541	FN9233ES	FN9255M	RWK212
FN283	FN2070	FN3287	FN3542	FN9233ES1	FN9255MB	RWK3044
FN284	FN2071	FN3288	FN3545	FN9233ES1B	FN9255S	RWK305
FN285	FN2080	FN3288HV	FN3840	FN9233ES1R	FN9255SB	RWK3062
FN286	FN2090	FN3288HVIT	FN385B	FN9233ESB	FN9260	C13-Locking-Outlet-1.5mm
FN286B	FN2091GB	FN3288IT	FN388B	FN9233ESR	FN9260A	C19-Locking-Outlet-1.5mm
FN286E	FN2092	FN3310	FN389B	FN9233EU	FN9260A1	SYNC300A
FN332	FN2200	FN3310HV	FN393E	FN9233EUB	FN9260B	SYNC300X
FN332Z	FN2210	FN3311	FN394E	FN9233R	FN9260S	CABINET 380-480VAC IP54 3W
FN343	FN2211	FN3311HV	FN5040	FN9233S	FN9260SA	CABINET 380-415VAC IP54 4W
FN350	FN2220	FN3311HVIT	FN5040HV	FN9233S1	FN9260SB	C13-4 Tier-Locking Outlet
FN351	FN2221	FN3311IT	FN5045	FN9233S1B	FN9262	C13-6 Tier-Locking Outlet
FN351H	FN2230	FN3359	FN5060	FN9233S1F2	FN9262A	
FN352Z	FN2231	FN3359B	FN5060HV	FN9233S1R	FN9262B	
FN354	FN2320Y	FN3359HV	FN610B	FN9233SB	FN9262S	
FN355	FN2410	FN3359HVB	FN6840	FN9233SF2	FN9262SA	
FN356	FN2412	FN3359HVPV	FN9222	FN9233SR	FN9262SB	
FN370	FN2415	FN3359PV	FN9222A	FN9233U	FN9263	
FN372	FN2450B	FN3410	FN9222AR	FN9233UB	FN9263S	
FN372B	FN2560	FN3410HV	FN9222B	FN9233UF2	FN9263S1	
FN375	FN2580	FN3411	FN9222E	FN9244	FN9264	
FN378	FN3021	FN3412	FN9222EB	FN9244B	FN9264B	
FN379	FN3025HL	FN3413	FN9222ER	FN9244E	FN9264S	
FN379B	FN3025HP	FN3416	FN9222ES	FN9244EA	FN9264SB	
FN380	FN3026HL	FN3416LV	FN9222ES1	FN9244EB	FN9266	
FN382	FN3100	FN3418	FN9222ES1B	FN9244ER	FN9266A	
FN382B	FN3120H	FN3418LV	FN9222ES1R	FN9244ES	FN9266B	
FN385	FN3256H	FN3420	FN9222ESB	FN9244ES1	FN9266S	
FN388	FN3258	FN3430	FN9222ESR	FN9244ES1B	FN9266SA	
FN389	FN3258A	FN3440	FN9222EU	FN9244ES1R	FN9266SB	
FN393	FN3258B	FN3441	FN9222EUB	FN9244ESB	FN9274B	
FN394	FN3258H	FN3442	FN9222R	FN9244ESR	FN9274MB	
FN409	FN3258P	FN3443	FN9222RA	FN9244EU	FN9274S1B	
FN420	FN3258Q	FN3450	FN9222RB	FN9244R	FN9280	
FN422	FN3258T	FN3451	FN9222S	FN9244S	FN9280B	
FN610	FN3258T1	FN3452	FN9222S1	FN9244S1	FN9280E	
FN612	FN3258T2	FN3453	FN9222S1B	FN9244S1B	FN9280EB	
FN660	FN3268	FN3470	FN9222S1R	FN9244S1R	FN9282-	
FN660B	FN3268I	FN3471	FN9222SB	FN9244SB	FN9284	
FN670	FN3268Q3	FN3472	FN9222SR	FN9244SR	FN9289	
FN682	FN3270H	FN3473	FN9222U	FN9244U	FN9289B	
FN685	FN3270HN	FN3480	FN9222UB	FN9246	FN9289E	
FN686	FN3270HQ1	FN3481	FN9222UZ	FN9246A	FN9289EB	
FN700Z	FN3270HQ2	FN3482	FN9226	FN9246B	FN9290	
FN1392	FN3270HT1	FN3483	FN9226B	FN9246EB	FN9290B	

The listed materials are being modified. Related materials that are not explicitly listed on this PCN are not being modified nor discontinued as per the PCN. If any questions, please ask according "Customer enquiries"